



RE: internal beam for day room query

From Darren Parrett <darren@lasebc.co.uk>
Date Thu 04/12/2025 08:50
To Jenny Prentice <jennymaryprentice@hotmail.com>

Hi Jenny,

Both Tim and I have reviewed the report which seems reasonable.


In respect of the beam and block flooring, generally we would like to come out to inspect the void under the beam and block flooring, means of crossflow ventilation for this void, damp-proofing arrangements as well as the general structural arrangement. This may be from installation work being in progress, or if the installation is complete, a couple of blocks left out so the void can be inspected. Photos taken during installation can also be helpful as these can be reviewed if required.

Kind regards

Darren

Darren Parrett

Building Control Surveyor



LSE Building Standards Ltd

A: The Office, Hogs Green, Sandling Road, Hythe Kent CT21 4HG
T: 01303 237704
M: 07742 048877
W: www.lasebc.co.uk

IMPORTANT: The contents of this email and any attachments are confidential. They are intended for the named recipient(s) only. If you have received this email by mistake, please notify the sender immediately and do not disclose the contents to anyone or make copies thereof.

LSE Building Standards Ltd is a company registered in England and Wales, under company No. 11500112, and registered Office One Step Beyond, Westfield Lane, Etchinghill, Kent CT18 8BT.